




00162468413041

ATV31/ATV312 Ferrites

VW3A31451...453



x 3

	ATV31	ATV312
VW3A31451	ATV31H018M2	ATV312H018M2
VW3A31452	ATV31H037M2 ATV31H018M3 ATV31H037M3	ATV312H037M2 ATV312H018M3 ATV312H037M3
VW3A31453	ATV31H055M2 ATV31H075M2 ATV31HU11M2 ATV31HU15M2 ATV31H055M3 ATV31H075M3	ATV312H055M2 ATV312H075M2 ATV312HU11M2 ATV312HU15M2 ATV312HU22M2 ATV312H055M3 ATV312H075M3 ATV312HU11M3 ATV312HU15M3 ATV312HU22M3

DANGER

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH


- Only appropriately trained persons who are familiar with and fully understand the contents of the present manual and all other pertinent product documentation and who have received all necessary training to recognize and avoid hazards involved are authorized to work on and with this equipment.
- Installation, adjustment, repair, and maintenance must be performed by qualified personnel.
- Verify compliance with all local and national electrical code requirements as well as all other applicable regulations with respect to grounding of all equipment.
- Before performing work and/or applying voltage on the equipment, follow the instructions given in the appropriate installation manual.

Failure to follow these instructions will result in death or serious injury.


Electrical equipment should be installed, operated, serviced, and maintained only by qualified personnel. No responsibility is assumed by Schneider Electric for any consequences arising out of the use of this product. © 2025 Schneider Electric. All Rights Reserved.

UK MANUFACTURER
CA Schneider Electric Industries SAS
35 rue Joseph Monier
Rueil Malmaison 92500 France


UK REPRESENTATIVE
Schneider Electric Limited
Stafford Park 5
Telford, TF3 3BL United Kingdom



1)



2)



3)

