

920/R55X
set di ricambio


 art.	
009200878	920/R55X meccanismo rotante cricchetti per 606/10X, 612X, 66/10X, 599DGT/10X 606/10X-612X 666/10X-599DGT/10X-599DGT-AN/10 665/10X-665LB/10X-666N10X-666N LBF.IN/10X 668RGC/10X-666 LBF.FT/10X 666HS/20LC-666HS/30LC

