

GB**ATTENTION**

**Dies must not be closed without
insertion of connector.**

F**ATTENTION**

**Les matrices ne doivent pas être serrées sans
connecteur.**

D**ACHTUNG**

**Presseinsätze nicht ohne Kabelschuh im
Leerlauf betätigen.**

E**ATENCIÓN**

**No se debe cerrar las matrices, sin haber
introducido antes el conector.**

I**ATTENZIONE**

**Mai mandare in battuta le matrici a vuoto,
senza connettore inserito.**


www.cembre.com

CEMBRE S.p.A.
via Serenissima, 9
25135 Brescia
Italy
Ph +39 030 36921
ufficio.vendite@cembre.com
sales@cembre.com

CEMBRE Ltd.
Dunton Park,
Kingsbury Road,
Curdworth, Sutton Coldfield
West Midlands, B76 9EB
United Kingdom
Ph +44 01675 470440
sales@cembre.co.uk

CEMBRE S.a.r.l.
22 Avenue Ferdinand
de Lesseps
91420 Morangis Cedex
France
Ph +33 01 60 49 11 90
info@cembre.fr

CEMBRE España S.L.U.
Calle Verano 6 y 8
Pl Las Monjas
28850 Torrejón de Ardoz
Madrid - Spain
Ph +34 91 4852580
comercial@cembre.com

CEMBRE GmbH
Geschäftsbereich
Energie- und Bahntechnik
Heidemannstr. 166
80939 München
Germany
Ph +49 89 3580676
info@cembre.de

CEMBRE GmbH
Geschäftsbereich
Industrie und Handel
Boschstraße 7
71384 Weinstadt
Germany
Ph +49 7151-20536-60
info-wj@cembre.de


CEMBRE Inc.
Raritan Center Business Park
300 Columbus Circle-S.F.,
Edison, NJ 08837 USA
Ph +1 (732) 225-7415
sales.us@cembre.com
Midwest Office
1051 Perimeter Dr #610
Schaumburg, IL 60173




50 kN / 60 kN

OK

CONNECTOR
CONNECTEUR
KABELSCHUH
CONECTOR
CONNETTORE




NO



130 kN

OK

CONNECTOR
CONNECTEUR
KABELSCHUH
CONECTOR
CONNETTORE



NO

